



Photos taken during the shipyard visit on 2025-04-08










This is a normal repair, as mooring with the bow towards the islands in the archipelago is commonly used


























































The painting and preparation of the hull above the waterline will be finalized at the home port









The chain for the emergency steering to be replaced with a new one



