

Truck Check Schema - Delga Verksted AS

Inspection Details

- Location:Oslo
- Date: 27.03.2025
- Mileage: 181746
- Order No.: 50006
- License Plate: KJ44164

Status:

- [1] - OK
- [2] - Repair recommended
- [3] - Repair immediately
- [X] – Not checked

Road Test

- [1] 1. Check before start
- [1] 2. Check during testdrive
- [2] 3. Check after testdrive

General Checks

- [2] 4. Check warning and control lamps
- [3] 5. Function check of parking heater
- [2] 6. Diangostic
- [x] 7. Complete vehicle, software update

External Check

- [2] 8. Check batteries - dirt, leakage, attachment, fluid level, connections and battery box
- [1] 9. Charge battery
- [1] 10. Check air intake and air deflector
- [2] 11. Check lighting and reflectors
- [2] 12. Check radar sensor
- [1] 13. Check engine oil level
- [1] 14. Check coolant frost protection and fluid level

Under Vehicle Check

- [1] 15. Check brake linings
- [1] 16. Check tyre wear
- [1] 17. Check brake calipers and brake discs

- [1] 18. Check brake cylinders, levers and forks
- [x] 19. Check air suspension bellows
- [1] 20. Check sealing of rear axle and hub reduction gear
- [1] 21. Check oil level in rear axle
- [2] 22. Check propeller shafts, universal joints, slide joints, and support bearings
- [x] 23. Check sealing of retarder
- [1] 24. Check exhaust pipe and silencer or particulate filter
- [1] 25. Check AdBlue system

Engine Bay Check

- [1] 27. Check fluid levels in windscreen and headlamp washer reservoirs
- [1] 28. Check drive belts and belt tensioners
- [x] 29. Check engine, engine-powered power take-off, and compressor for leakage
- [1] 30. Check fuel piping and lines
- [1] 31. Check hoses and pipes for the charge air cooler
- [1] 32. Check radiator, hoses, and pipes
- [1] 33. Check for exhaust leakage

Component Status

Clutch Status

Clutch: [x] Good [] Needs Attention

Battery Status

Battery Condition: [] Good [x] Needs Attention

Brake Pads (%)

Front: 50 %

Rear: 50%

Brake Discs (%)

Front: % visual - OK

Rear: % visual - OK


Tyre Measurements (mm)

A1: 5-5 mm

A2: 8-9 mm

A3: mm

DAMAGES



Additional Comments:

Webasto does not start.

Small scratches.

The vehicle is in good condition.

Technician Signature: E.V

Date: 27.03.2025

Delga Verksted AS